



SECTION A-A

NOTE:

**LINE ϕ OF STRIKE WITH
 ϕ OF BOLT**

HOLE ARRANGEMENT FOR 4700 SERIES

LOCK FUNCTION	OUTSIDE	INSIDE
4775	CYLINDER	THUMTURN
4774	CYLINDER	CYLINDER
4777	CYLINDER	CYLINDER
4778	CYLINDER	-----
4779	-----	THUMBTURN

Not to Scale

The use of non-clutching impact drivers to install this hardware will automatically void the warranty.